



























Biweekly Field Report

Surveyor Zaw La
 Date visited 25 Jul 2018
 Time visited 15 : 00pm





Weather Condition Cloudy
 The last time of heavy raining Yesterday

No	Item	Condition	Description and Photos
1	(1) Well	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	– Water from two open-wells is clean and can be used for drinking and living. There are eleven tube wells in the relocation site. People mainly use water from pipeline water distribution system so that no body use the tube wells and JET asked them to let know if the tube wells are needed to repair.
			<div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>Open Well No. 1</p> </div> <div style="width: 50%; text-align: center;">  <p>Open Well No. 2</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 1</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 2</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 3</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 4</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 5</p> </div> <div style="width: 50%; text-align: center;">  <p>Tube Well No. 10</p> </div> </div>





			 Tube Well No.11	 Tube Well No.7
(2) Drainage	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p>– There is a little water in the drainage canals at the moment.</p> <p>Photos</p>	 Drain at the corner of Main Road A and B	 Drain exit at the corner of Site village road and 2 nd street
			 Drain exit at the corner of Site village road and 3 rd	 Drain exit at the corner of Site village road and Main Road C
(3) Road	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<p>– All the roads are a bit wet, however no problem for walking except road no. 6 which has some muddy places so that where need to be careful to walk across on it.</p> <p>Photos</p>	 Main Road - B	 1 st Street














			 <p>2nd Street Upper Block</p>	 <p>2nd Street Lower Block</p>
			 <p>3rd Street Upper Block</p>	 <p>3rd Street Lower Block</p>
			 <p>4th Street Upper Block</p>	 <p>4th Street Lower Block</p>
			 <p>5th Street</p>	 <p>6th Street</p>
			 <p>7th Street</p>	 <p>Site Village Road</p>

(4)	Garbage Condition	Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/> * Worse <input type="checkbox"/> <i>*as last week</i>	<ul style="list-style-type: none"> – People throw garbage beside the creek and even in front of their houses before they got enough garbage bins. – There are fourteen garbage bins are provided and they are kept at the corner of each road until the end of April and now all the garbage bins are kept in the communal compound near side road C by PAP community leader. During this raining season, people must keep garbage in its own house until the garbage collection car comes. <p>Photos</p>
			<div data-bbox="555 452 967 743" data-label="Image"> </div> <div data-bbox="555 743 967 828" data-label="Caption"> <p>Rubbish at the creek near 1st street</p> </div> <div data-bbox="1002 452 1414 743" data-label="Image"> </div> <div data-bbox="1002 743 1414 828" data-label="Caption"> <p>Rubbish at the creek near 2nd street</p> </div>
			<div data-bbox="555 869 967 1146" data-label="Image"> </div> <div data-bbox="555 1146 967 1232" data-label="Caption"> <p>Rubbish at the creek near Main Road C</p> </div> <div data-bbox="1002 869 1414 1146" data-label="Image"> </div> <div data-bbox="1002 1146 1414 1232" data-label="Caption"> <p>Rubbish at the creek near 6th Street</p> </div>

<p>(5) Fly proof toilet</p>	<p>Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/>* Worse <input type="checkbox"/> <i>*as last week</i></p>	<ul style="list-style-type: none"> - All of the fly proof toilets are used by people. - All the toilets are repaired with extra septic tanks, pipe line system connected to the ditch for overflow liquid from the extra septic tanks. The toilet renovation was successfully done and there is no problem in the moment. <table border="1" data-bbox="552 277 1235 573"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHS</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>91</td> <td>91</td> </tr> <tr> <td>Level 2</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>0</td> <td>0</td> </tr> <tr> <td>No Toilet</td> <td>0</td> <td>0</td> </tr> </tbody> </table> <p><Evaluation Criteria></p> <p>Level 1</p> <ul style="list-style-type: none"> - Fly proof toilet is not needed to be repaired. -No/rarely toilet unavailable <p>Level 2</p> <ul style="list-style-type: none"> - Fly proof toilet is needed to be repaired. -Rarely toilet unavailable <p>Level 3</p> <ul style="list-style-type: none"> -- Fly proof toilet is needed to be repaired. -Often toilet unavailable -As the result of filling the soil and also due to the heavy rain, some toilets are inconvenience to use. <p>Level 4</p> <ul style="list-style-type: none"> - Fly proof toilet is urgently needed to be repaired. -Often toilet unavailable <p>Photos</p> <div style="display: flex; flex-wrap: wrap;"> <div style="width: 50%; text-align: center;">  <p>House No. 81</p> </div> <div style="width: 50%; text-align: center;">  <p>House No. 37</p> </div> <div style="width: 50%; text-align: center;">  <p>House No. 31</p> </div> <div style="width: 50%; text-align: center;">  <p>House No. 21</p> </div> </div>	Condition	No. of HHS		This week condition	Previous week condition	Level 1	91	91	Level 2	0	0	Level 3	0	0	Level 4	0	0	No Toilet	0	0
Condition	No. of HHS																					
	This week condition	Previous week condition																				
Level 1	91	91																				
Level 2	0	0																				
Level 3	0	0																				
Level 4	0	0																				
No Toilet	0	0																				
<p>(6) Electricity</p>	<p>Improved <input type="checkbox"/> Same <input checked="" type="checkbox"/>* Worse <input type="checkbox"/> <i>*as last week</i></p>	<ul style="list-style-type: none"> - Electricity comes regularly. - Electric poles and transformer are being supported with a good foundation. - There are some pieces of wood under an electric pole of main road B that need to clean up. <p>Photos</p>																				

			 <p>Transformer No. 1</p>	 <p>Transformer No. 2</p>
			 <p>Transformer No. 3</p>	 <p>Electricity poles of Main Road B and Main Road C</p>

No	Item	Condition	Description and Photos
2	(1)House Construct-ion	No. of houses not completed (4)	<ul style="list-style-type: none"> – House No.9, there are three houses that planned to build in plot number 9 and 10 as the plots are owned by father and son. The two houses finished construction and left one. – House No.64, the house construction seems to be stopped. – House No. 78, the house need to be carried on construction, however PAPs are living now. – House No. 66, the house construction for first floor has been finished and the second floor is needed to be carried on. <p>Photos</p>  <p>House No. 9</p>  <p>House No. 64</p>  <p>House No.</p>  <p>House No. 66</p>

3	Other Issues																							
	(1). Drainage condition for rain water in their compounds	<p><u>Description</u></p> <table border="1" data-bbox="560 208 1145 465"> <thead> <tr> <th rowspan="2">Condition</th> <th colspan="2">No. of HHs</th> </tr> <tr> <th>This week condition</th> <th>Previous week condition</th> </tr> </thead> <tbody> <tr> <td>Level 1</td> <td>87</td> <td>87</td> </tr> <tr> <td>Level 2</td> <td>3</td> <td>3</td> </tr> <tr> <td>Level 3</td> <td>0</td> <td>0</td> </tr> <tr> <td>Level 4</td> <td>1</td> <td>1</td> </tr> </tbody> </table> <p><Evaluation Criteria> Level 1 -No mud and no standing water with their own drainage system in their compound Level 2 -No mud and no standing water in their compound Level 3 - Some or little mud and standing water in their compound Level 4 -A lot of mud and standing water in their compound</p> <p><u>Photos</u></p> <table border="1" data-bbox="560 947 1441 1592"> <tr> <td data-bbox="560 947 1007 1261"> <p>Level 1</p>  <p>House No. 31</p> </td> <td data-bbox="1007 947 1441 1261"> <p>Level 2</p>  <p>House No. 19</p> </td> </tr> <tr> <td data-bbox="560 1261 1007 1592"> <p>Level 3</p>  <p>House No. 47</p> </td> <td data-bbox="1007 1261 1441 1592"> <p>Level 4</p>  <p>House No. 64</p> </td> </tr> </table>		Condition	No. of HHs		This week condition	Previous week condition	Level 1	87	87	Level 2	3	3	Level 3	0	0	Level 4	1	1	<p>Level 1</p>  <p>House No. 31</p>	<p>Level 2</p>  <p>House No. 19</p>	<p>Level 3</p>  <p>House No. 47</p>	<p>Level 4</p>  <p>House No. 64</p>
Condition	No. of HHs																							
	This week condition	Previous week condition																						
Level 1	87	87																						
Level 2	3	3																						
Level 3	0	0																						
Level 4	1	1																						
<p>Level 1</p>  <p>House No. 31</p>	<p>Level 2</p>  <p>House No. 19</p>																							
<p>Level 3</p>  <p>House No. 47</p>	<p>Level 4</p>  <p>House No. 64</p>																							
		<p>Level 3</p>  <p>House No. 75</p>																						

(2) Plantation

- In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.



Description

-In front of their compounds, the people planted shady trees, fruit trees, vegetables and floral plants.

Type	No. of HHs	Remarks
Shady tree	15	Albizzia, Indian almond, neem tree, etc. HH No. 20, 40, 43, 48, 51, 57, 59, 61, 62, 67, 69, 72, 73, 77, 85
Fruit tree	37	Banana, Mango, sugarcane, coconut, citrus, jack fruit etc. HH No. 3, 15, 17, 20,21, 23, 28, 30, 31, 32, 34, 37, 40, 41, 48, 51, 52, 55, 57, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 78, 82, 85, 86, 88
Vegetable	20	Chili, tomato, bitter gourd, Roselle, gourd, basils, eggplant etc. HH No. 12, 17, 21, 41, 49, 58, 59, 61, 62, 63, 67, 68, 70, 71, 72, 73, 77, 82, 85, 86
Floral plant	31	Jasmine, poinsettia, orchid, kiss me quick, etc. HH No. 3, 5, 6, 8, 10, 12, 13, 14, 17, 20, 21, 22, 23, 29, 30, 31, 32, 46, 48, 58, 59, 61, 62, 65, 67, 68, 69, 72, 77, 78, 86

Photos,



(3) Livestock	Description -The people are raising chicken, geese and ducks.												
	<table border="1"> <thead> <tr> <th>Type</th> <th>No. of HHs</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>Chicken</td> <td>6</td> <td>HH No. 13, 14, 21, 59, 67, 78</td> </tr> <tr> <td>Duck</td> <td>3</td> <td>HH No.12</td> </tr> <tr> <td>Goose</td> <td>2</td> <td>HH No. 40, 67</td> </tr> </tbody> </table>	Type	No. of HHs	Remarks	Chicken	6	HH No. 13, 14, 21, 59, 67, 78	Duck	3	HH No.12	Goose	2	HH No. 40, 67
Type	No. of HHs	Remarks											
Chicken	6	HH No. 13, 14, 21, 59, 67, 78											
Duck	3	HH No.12											
Goose	2	HH No. 40, 67											
	Photos												
	 <p>House No. 67</p>	 <p>House No. 12</p>											